

General Environmental Incident Summary

Incident: 3688 **Date/Time Notice:** 3/18/2015 **DEM Incident No:**

Responsible Party: Marathon Oil

Date Incident: 3/17/2015 **Time Incident:** 1700 **Duration:**

County: Dunn **Twp:** 148 **Rng:** 96 **Sec:** 12 **Qtr:**

Lat: 47.65001 **Long:** -102.85020 **Method:** Navigation quality GPS

Location Description: Morean USA 34-12H

Submitted By: Chris Gitch

Affiliation: Marathon Oil

Address: 3172 Highway 22 N.

City: Dickinson

State: ND

Zip: 58601

Received By:

Contact Person: Chris Gitch
3172 Highway 22 N.
Dickinson, ND 58601

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Hydraulic Oil

Volume Spilled: 38.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Ensign 161, Drilling- AREI - Hydraulic Spill - Pump Failure On Standby Pump Truck- Morean USA 34-12H

During cement operations a standby pump truck developed a hydraulic leak from the servo box. The release wasn't discovered immediately due to the truck being used as a backup. Once discovered, MOC Site Supervisor and HES Advisor were notified. 38 gallons of hydraulic oil was released to unprotected ground. Clean-up is underway and no fluids left location. Proper agency notifications have been made.

Risk Evaluation:

No immediate risk. Spill has been cleaned up.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

No potential environmental impact. Spill has been cleaned up.

Action Taken or Planned:

Spill has been cleaned up by contractor and disposed of at approved facility

Wastes Disposal Location: Waste will be disposed of at approved facility by contractor

Agencies Involved: BLM, MHA Energy,

Updates

Date: 3/18/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Volume:

Notes:

Tank leak on a well site. NDIC retains oversight. Forwarded to NDIC.